

R.G.& B.A. PARKER
P.O.BOX 92
ASPLEY 4034.
12th MAY,1993

The Manager

Dear Sir,

We recently installed a new Yanmar 2 GM20 engine to our Compass-29 Yacht. Despite the alignment of gearbox and shaft being correct, there seemed to be excessive engine movement in the 1500/1700 R.P.M.range. We then had the shaft checked for alignment and propeller balanced. However the movement persisted. We always felt that the original mounts as supplied were too soft. After discussing the problem with you it was decided to install the "Y" Series Poly Flex mounts together with a PolyFlex coupling. We are pleased to advise that the problem has been solved. The engine now runs smoothly through its full range.

Thank you for your advise and recommendation to install Poly Flex engine mounts and coupling to our yacht.

Yours faithfully,

A handwritten signature in black ink, appearing to read 'R.G. Parker', written over a horizontal line.

R.G. Parker.